
SKIN PROTECTION: For brief contact to dust, no precautions other than clean body-covering clothing should needed

Suggestion method after products will be discarded:

1. Separate reuse method: crush products into powder then separate the valued copper, recycling left plastic powder as a filler.
2. Incineration method: incinerate the unused products, this method may produce some organic